



Yamada America, Inc.
955 East Algonquin Rd
Arlington Heights, IL 60005
Phone: 847.631.9200
Fax: 847.631.9273
www.yamadapump.com

Model: DP-10BAN
Part # 851841



Reference			
No.	Description	Q'ty	Part No.
1	Hexagon Socket Bolt	8	681295
2	Spring Lock Washer	20	681300
3	Plain Washer	20	631329
4	O-ring	4	643018
5	Valve Stopper	4	771368
6	Ball	4	770972
7	Valve Seat	4	710638
8	O-ring	4	643017
9	Center Disk	2	708770
10	Nut	2	681849
11	O-ring	4	640005
12	Coned Disk Spring	2	684916
13	Center Disk	2	709512
14	Sleeve	1	714678
15	O-ring	4	684900
16	Pump Base	2	710586
17	Cushion	4	771123
18	Hexagon Socket Head Plug	2	709872
19	Manifold	2	802591
20	Body	1	715107
21	Retaining Ring R Type	2	630807
22	Packing	4	684284
23	O-ring	2	640131
24	Spacer	1	772651
25	Center Rod Assembly	1	801785
26	Guide Bush	2	772619
27	Diaphragm	2	770973
28	Out Chamber	2	710572
29	Spring Lock Washer	6	681855
33	Valve Body Assembly	1	804505
33-1	Push Rod	1	706798
33-2	Reinforcement Plate A	1	710587
33-3	Cap	1	771357
33-4	Spool Valve Case	1	710853
33-5	Spool Valve Assembly	1	801404
33-6	Cap	1	771356
33-7	Reinforcement Plate B	1	710636
33-8	Spring Lock Washer	4	681855
33-9	Hexagon Socket Head Bolt	4	682943
34	Hexagon Socket Head Bolt	2	682918
36	Ball Valve	1	683055
41	Bolt	4	621102
42	Plain Washer	4	631328
43	Nut	4	628010
44	Gasket	1	771358
45	Hexagon Socket Head Bolt	12	682944
46	Silencer	1	682520

Repair Kits			
K10-AN Liquid Side Kit includes the following:			
4	O-ring	4	643018
6	Ball	4	770972
8	O-ring	4	643017
11	O-ring	4	640005
27	Diaphragm	2	770973
K115-AM Air Side Kit includes the following:			
15	O-ring	4	684900
22	Packing	4	684284
23	O-ring	2	640131
33-5	Spool Valve Assembly	1	801404
44	Gasket	1	771358

Yamada America, Inc.
955 East Algonquin Rd
Arlington Heights, IL 60005
Phone: 847.631.9200
Fax: 847.631.9273
www.yamadapump.com